



System Diagnostics Information Update

When the 850-megahertz (MHz) microprocessor is installed and the system diagnostics are run, floating point unit (FPU) exception errors are sometimes generated. These are false errors and should be ignored.

**Information in this document is subject to change without notice.
© 2001 Dell Computer Corporation. All rights reserved. Printed in the U.S.A.**

Reproduction in any manner whatsoever without the written permission of Dell Computer Corporation is strictly forbidden.

Trademarks used in this text: *Dell* and the *DELL* logo are trademarks of Dell Computer Corporation. Other trademarks and trade names may be used in this document to refer to either the entities claiming the marks and names or their products. Dell Computer Corporation disclaims any proprietary interest in trademarks and trade names other than its own.

www.dell.com

support.dell.com

P/N 6G061 Rev. A00
May 2001



06G061 A00

